



- A. ADD CURB, FIX DRAINAGE, AND REPLACE EXISTING SWINGS
- B. CONCRETE APPROXIMATELY 530' OF TRAIL TO REDUCE WASHOUTS AND IMPROVE MAINTENANCE ACCESS
- C. REPLACE EXISTING MAINTENANCE ENTRANCE WITH WIDENED CONCRETE ACCESS TO SHELTER
- D. GENERAL RESTROOM IMPROVEMENTS (FIXTURES, LIGHTS, ROOF, ADA STANDARDS, ETC.)
- E. REPLACE EXISTING PLAYGROUND WITH AGE 2-5 YEAR OLD PLAYGROUND
- F. DISC GOLF PLAZA (COURSE OVERVIEW, SINGLE SHELTER, BENCHES)
- G. DISC GOLF COURSE INFRASTRUCTURE IMPROVEMENTS